

### **Background Information:**

- **♦** Adopted Complete Streets Policy in 2017.
- Approved Complete Street Prioritization Plan in 2022.

#### **Crash Stats (2018-2023)**



#### 798

total crashes

pedestrian crashes

bicyclist crashes

motorcyclist crashes



#### 2

fatal crashes

pedestrian crash



#### 20

serious injuries

**3** pedestrian crashes

bicyclist crash

motorcyclist crash

### **Fatal/Serious Injuries**

18% occurred during dark lighting conditions (lighted roadway/not lighted)

55% occurred under the jurisdiction of MassDOT

14% occurred along Minor Arterial Roads and 55% occurred along Principal Arterial – Other Roadways

36% of the crashes are single-vehicle crashes

27% of the crashes contributing factors were either reckless/speeding/distracted/impaired

1 crash was collision with utility pole, 1 crash was collision with tree


#### **Public Comments**

- Install sidewalk facilities along Samoset Road to provide a path to Eastham Public Library.
- Route 6 between Orleans
  Rotary and Samoset Road
  is unsafe, 4-lane undivided
  roadway with a posted speed
  limit of 40 mph, which motor
  vehicles travel above that, no
  shoulders or left-turn lanes
  available, along with no bicycle
  facilities and safe crossings.
- The existing HAWK signal along Route 6 south of Governor Prence Road, motor vehicles do not stop for pedestrian crossing.


- Description improve the two-way STOP controlled at the of Route 6 at Governor Prence Road with a traffic signal and multimodal elements. The traffic signal here will help to break up traffic and make it easier to access the side streets.
- Description Improve the AWSC at Herring Brook Road at Samoset Road to include multimodal elements and consideration for a traffic signal.
- Route 6 should include sidewalk and bicycle facilities and more midblock crossings.

High Risk Corridors					
Brackett Road	Nauset Road				
Bridge Road	Old County Road				
Eastham Rotary	Old Orchard Road				
Grand Army of the Republic Highway (Route 6)	Samoset Road				
Herring Brook Road	Schoolhouse Road				
Massasoit Road					

## **High Risk Network**



## **High Injury Network**





# EASTHAM - OUTER CAPE

HIN – Corridor/ Intersection	Jurisdiction	Length (miles)	Characteristics	Contributing Factors	Studied/ Previous Planning	Potential Countermeasures
Brackett Road from Route 6 to Nauset Road	Local / MassDOT (Route 6)	0.93	<ul> <li>2-lane undivided roadway</li> <li>Posted speed limit: 35 mph</li> <li>No sidewalk/ designated bicycle facilities, but includes signage "SHARE THE ROAD"</li> <li>Narrow to no shoulders</li> <li>Commercial land use at western end and residential land use remainder</li> <li>38 total crashes (3 serious injuries, 5 bicyclists, 1 pedestrian)</li> </ul>	Operating vehicle in erratic, reckless, careless, negligent or aggressive manner/ Disregarded traffic signs, signals, road markings/ Inattention/ Failure to keep in proper lane or running off road/ Failed to yield right of way/ Exceeded authorized speed limit	Complete Streets Project (Construct sidewalk connections to the Cape Cod Rail Trail)	Install speed feedback signs near Route 6 and Nauset Road, along Brackett Road     Install green sharrows with pavement markings     Identify locations near the residential land use for midblock crossings and inclusion of RRFB     Install wider edge lines (6 inches)      Long-Term      Install speed table/cushion near Cape Cod Rail Trail on both sides     Install sidewalk facilities along the entire corridor (at least one side)     Improve signalized intersection, Brackett Road at Route 6, addition of turn lanes, backplates with retroflective borders, & etc.     Consideration of tighten curb radii Brackett Road at Nauset Road
Samoset Road from Herring Brook Road to Route 6*	Local / MassDOT (Route 6)	1.26	<ul> <li>2-lane undivided roadway</li> <li>Posted speed limit: 25/30 mph</li> <li>No sidewalk/ designated bicycle facilities, No white edge lines</li> <li>Residential land use</li> <li>15 crashes (3 bicyclists, 2 pedestrians)</li> <li>Cape Cod Rail Trail crossing along Samoset Road</li> </ul>	Inattention/ Operating vehicle in erratic, reckless, careless, negligent or aggressive manner/ Made an improper turn/ Failure to keep in proper lane or running off road	Complete Streets Project (Construct sidewalk connections to the Cape Cod Rail Trail and improve pedestrian crossings)  * Samoset Road will be resurfaced within 1 year.	Short-Term  Remove overgrown vegetation along route Update the guardrail on the north side near Lawton Road Identify locations near the residential land use for midblock crossings and inclusion of RRFB Install advisory speed signage (W13-1P) at curvatures, such as near Lawton Road, Great Pond Road Add pavement markings and STOP (R1-1) sign placement AWSC Samoset Road at Herring Brook Road Install wider edge lines (6 inches)  Long-Term Improve the one-way STOP (R1-1) control at Samoset Road at Lawton Road Install shared use path along entire corridor Improve yield controlled Samoset Road at Depot Road Install speed table/cushion near Cape Cod Rail Trail on both sides
Cable Road at Nauset Regional High School	National Seashore (Federal Government)		<ul> <li>Two (2) access points to Nauset Regional High School</li> <li>Cable Road Posted speed limit: 30 mph</li> <li>18 crashes</li> </ul>	Inattention/Made an Improper turn Complete Streets Project (Construct sidewalk to the Three Sisters Lighthouse	Complete Streets Project (Construct sidewalk to the Three Sisters Lighthouse)	Short-Term  Initiate conversation with SRTS program to be a partner school  Long-Term  Install green sharrows with pavement markings Install sidewalk facilities along the entire corridor (at least one side)
Route 6 from Pheasant Run to Aspinet Road	MassDOT	4.34	<ul> <li>4-lane undivided roadway</li> <li>358 crashes (1 fatal, 12 serious injuries, 3 bicyclists, 4 pedestrian)</li> <li>Sidewalk facilities on one side, unmaintained with overgrown greenery</li> <li>Posted speed limit: 40 mph</li> </ul>	Failed to yield right of way/ Visibility obstructed/ Swerving or avoiding due to wind, slippery surface, vehicle, object, vulnerable user in roadway/Wrong side or wrong way/ Operating vehicle in erratic, reckless, careless, negligent or aggressive manner/ Inattention/ Exceeded authorized speed limit/ Failure to keep in proper lane or running off road	Town of Eastham, Route 6 Corridor Improvement Project, 2021	Short-Term      Conduct a corridor Road Safety Audit (improvements may include adjustments to road alignments to improve sight distance, evaluation of traffic signal, signal visibility, proper placement and clarify of warning and regulatory signs, improvements in intersection designs, addition of turn lanes & etc, improvements of sidewalks, crosswalks, and bike lanes, & etc.)     Increase police presence during peak seasons  Long-Term      Consider road diet to include a raised shared use path, landscape buffer zone, two-lane divided roadway (mountable or raised median island), and a sidewalk     Implement actions from the Town of Eastham, Route 6 Corridor Improvement Project