BARNSTABLE

Background Information:

- Adopted Complete Streets Policy in 2022 Approved Complete Streets Prioritization Plan in 2023.
- Hyannis Great Streets establishes a new network that hinges from and supports a redesigned Main Street.
- Route 132 Corridor Study, 2024, improving multimodal transportation accommodations to create a corridor that safely serves a sense of place for people driving, walking, and bicycling along the roadway.
- Local Bottleneck Reduction Project Plans Intersection Improvements Main Street at Old Colony Road/ Center Street and Main Street at Camp Street / Lewis Bay Road.
- Town of Barnstable received FHWA SS4A grants to conduct road safety audits of 14 high-risk intersections for vehicles, bicycles and pedestrians.

Fatal/Serious Injuries

39% of the fatal/serious injuries occurred during dark conditions (lighted roadway/not lighted)

30% of the fatal/serious injuries occurred under the jurisdiction of MassDOT

24% occurred along Minor Arterial Roadways and 11% occurred along Principal Arterial – Other Roadways

50% of the crashes are single-vehicle crashes

54% of the crashes contributing factors were either reckless/speeding/distracted/impaired

20 crashes were collision with tree, 13 crashes were collision with utility pole

Crash Stats (2018-2023)



6,604

total crashes

- 123 pedestrian crashes
- 107 bicyclist crashes
- motorcyclist crashes



15

fatal crashes

- 2 pedestrian crashes
- bicyclist crash
- motorcyclist crashes




120

serious injuries


- 22 pedestrian crash
- **9** bicyclist crashes
- motorcyclist crashes

High Risk Network



High Risk Corridors						
Airport Rotary	Lewis Bay Road	Putnam Avenue				
Barnstable Road	Main Street	Race Lane				
Bearses Way	North Street	Scudder Avenue				
Bearses Way	Ocean Street	Sea Street				
Bumps River Road	Old Colony Road	South Street				
Charles Street	Old Post Road	Stevens Street				
Chestnut Street	Old Stage Road	Strawberry Hill Road				
Church Street	Old Town Road	Wakeby Road				
Craigville Beach Road	Phinneys Lane	West Main Street				
Falmouth Road	Pitchers Way	Yarmouth Road				
lyannough Road	Pond Street					

High Injury Network



A	Barnstable Road from Old Colony Road to Falmouth Road (Route 28)/ Airport Rotary	G	Santuit Newtown Road from Falmouth Road (Route 28) to Sandwich Townline
В	Bearses Way from Falmouth Road (Route 28) to Iyannough Road (Route 132)	H	West Main Street from Falmouth Road (Route 28) to Pitchers Way
C	Race Lane from Crocker Road to Old Stage Road	0	Falmouth Road (Route 28) from Mashpee Townline to Airport Rotary
D	lyannough Road (Route 132) from Bearses Way to Airport Rotary	J	lyannough Road (Route 132) from Route 6 to Bearses Way
E	North Street from Main Street to Barnstable Road	K	lyannough Road (Route 28) from Airport Rotary to Yarmouth Townline
F	Main Street from West End Rotary to Bayview Street		Main Street (Route 6A) from Hyannis Barnstable Road to Yarmouth Townline

BARNSTABLE - MID CAPE

HIN – Corridor/ Intersection	Jurisdiction	Length (miles)	Characteristics	Contributing Factors	Studied/ Previous Planning	Potential Countermeasures
Barnstable Road from Old Colony Road to Falmouth Road (Route 28)/ Airport Rotary	Local/MassDOT (Airport Rotary)	0.90	 2-lane undivided (mostly) roadway Posted Speed Limit: 30 mph Sidewalk facilities on both sides Limited on-street parking 205 crashes (3 serious injuries, 13 bicyclists, 11 pedestrians) 	Operating vehicle in erratic, reckless, careless, negligent or aggressive manner/ Wrong side or wrong way/ Inattention/ Disregarded traffic signs, signals, road markings/ Made an improper turn/ Followed too closely/ Failure to keep in proper lane or running off road/ Failed to yield right of way/ Distracted	Complete Streets Project (Assess and upgrade pedestrian facilities) HSIP Cluster – South Street at Ocean Street	Short-Term Assess midblock crosswalk locations (existing/proposed) and potential addition of RRFBs Install transverse pavement markings (series or lines) at key locations SS4A Road Safety Audit (RSA) location), Barnstable Road at Charles Street/Center Street Evaluate if the on-street parking (east side) by North Street needs to be removed or relocated Barnstable Road Corridor Improvements – Design and Permitting per CIP FY 2026 Incorporate RSA recommendations Airport Rotary Long-Term Enhance the corridor with streetscape improvements (street trees, benches & etc) Incorporate multimodal accommodations at Airport Rotary (TIP 610926 Airport Rotary Retrofit) Intersection improvements (roundabout) South Street at Old Colony Road/Ocean Street
Bearses Way from Falmouth Road (Route 28) to Iyannough Road (Route 132)	Local/ MassDOT (Route 28/ Route 132)	0.89	 2- lane undivided roadway Posted Speed Limit: 35 mph Sidewalk facilities on both sides Limited bicycle facilities 116 crashes (1 fatal, 2 serious injuries, 3 bicyclists) 	Operating vehicle in erratic, reckless, careless, negligent or aggressive manner/ Followed too closely/ Failed to yield right of way/ Disregarded traffic signs, signals, road markings/ Failed to yield right of way/ Distracted	Funded - TIP, Planning - Complete Streets (Construct a new SUP)	Intersection improvement Bearses Way at Enterprise Road (determine if SB approach needs to be remarked) or tighten curb radii Update traffic signals; backplates with retroreflective borders, signal timing changes, modern pedestrian signal equipment Bearses Way at Enterprise Road Install shared use path on the west side and installation of lighting Install RRFB at mid-block crosswalk to Cumberland Farms Long-Term Intersection improvement (roundabout) Bearses Way at Pitchers Way, applied for MassDOT Bottleneck Improvement Program
Race Lane from Crocker Road to Old Stage Road	Local	2.38	 2-lane undivided roadway Posted Speed Limit: 40 mph 115 crashes (1 fatal, 7 serious injuries, 1 bicyclist, 2 pedestrians) 	Operating vehicle in erratic, reckless, careless, negligent or aggressive manner/ Failure to keep in proper lane or running off road/ Failed to yield right of way/ Followed too closely/ Exceed authorized speed limit/ Driving too fast for conditions	Complete Streets Project (Construct a new SUP) HSIP Cluster – Race Lane at Old Stage Road	Short-Term Install transverse pavement markings (series or lines) at key locations Install solar speed feedback sign Remove MUTCD S1-1 School Crosswalk signs by 885 Race Lane Long-Term Install shared use path Intersection improvement Race Lane at Old Stage Road/Old Falmouth Road (SS4A RSA location) and Race Lane at Osterville-West Barnstable Road
lyannough Road (Route 132) from Bearses Way to Airport Rotary	Local/MassDOT (Airport Rotary)	1.19	 4-lane undivided roadway Business District 30 mph 427 crashes (5 serious injuries, 8 bicyclists, 20 pedestrians) 	Visibility obstructed/ Wrong side or wrong way/ Over-correcting/Over Steering/ Operating vehicle in erratic, reckless, careless, negligent or aggressive manner/ Made an improper turn/ Inattention/ Failed to yield right of way/ Disregarded traffic signs, signals, road markings/ Followed too closely/ Distracted	Complete Streets Project (Construct a new SUP and upgrade pedestrian facilities) HSIP Pedestrian Cluster – near Iyannough Road at Nightingale Lane	Short-Term Update traffic signals; backplates with retroreflective borders, signal timing changes, modern pedestrian signal equipment lyannough Road at Festival at Hyannis Driveway, lyannough Road at The Landing Driveway Incorporate elements from the Route 132 Corridor Study, 2024 to accommodate vehicles, bicycles, pedestrians. Long-Term Corridor Improvements and in the preliminary design phase (TIP 612960) Incorporate elements from the Route 132 Corridor Study, 2024 to accommodate vehicles, bicycles, pedestrians. Incorporate RSA recommendations at the Route 132 from east of Bearse's Way to west of Airport Rotary
North Street from Main Street to Barnstable Road	Local	0.84	 2-lane undivided roadway Sidewalk facilities 157 crashes (2 serious injuries, 2 bicyclists, 9 pedestrians) 	Failed to yield right of way/ Followed too closely/ Operating vehicle in erratic, reckless, careless, negligent or aggressive manner/ Inattention/ Failed to yield right of way/ Failure to keep in proper lane or running off road/ Distracted	Complete Streets Project (Upgrade pedestrian facilities) HSIP Clusters – North Street at Stevens Street, North Street at Bassett Lane	Short-Term Update traffic signals; backplates with retroreflective borders, signal timing changes, modern pedestrian signal equipment North Street at Bassett Lane, North Street at High School Road Ext, North Street at Winter Street, inclusion of decorative crosswalk markings SS4A RSA location North Street at Stevens Street and North Street from west of Winter Street to Sea Street Extension Remove on-street parking space in front of North Street approach by Barnstable Road Incorporate elements from the Hyannis Great Streets at the West Main Street Rotary such as the bike lane pavement marking and along North Street from Main Street to Barnstable Road. Long-Term Implement the Hyannis Great Streets. Intersection improvement North Street at Stevens Street Install shared use path from West End Rotary to Steven Streets

BARNSTABLE - MID CAPE

HIN – Corridor/ Intersection	Jurisdiction	Length (miles)	Characteristics	Contributing Factors	Studied/ Previous Planning	Potential Countermeasures
Main Street from West End Rotary to Bayview Street	Local	1.44	 2-lane undivided roadway Sidewalk facilities on both sides Includes white edge line Includes signage "motorists give 4 feet to pass" Limited section includes on- street parking Includes wayfinding and placemaking signage "Hyannis Main Street" 302 crashes (7 serious injuries, 13 bicyclists, 12 pedestrians) 	Operating vehicle in erratic, reckless, careless, negligent or aggressive manner/ Inattention/ Failed to yield right of way/ Disregarded traffic signs, signals, road markings/ Failure to keep in proper lane or running off road/ Followed too closely/ Driving too fast for conditions/ Distracted		Short-Term Main Street from West End Rotary to Center Street/Old Colony Road is part of the Hyannis Great Streets, which has been designed. SS4A RSA Location Main Street from Old Colony Road/Center Street to Camp Street and Main Street at High School Road. Conduct a RSA Main Street at Lewis Bay Road/Camp Street Long-Term Implement the Hyannis Great Streets. Incorporate RSA recommendations at the West End Rotary such as providing multimodal accommodations, reconstructing to a modern roundabout, considering design to improve deflection, signage and pavement marking, and curb cuts
Santuit Newtown Road from Falmouth Road (Route 28) to Sandwich Townline	Local / MassDOT (Route 28)	3.09	 2-lane undivided roadway Posted Speed Limit: 30 mph Limited sidewalk facilities Includes white edge lines 28 crashes 	Operating vehicle in erratic, reckless, careless, negligent or aggressive manner/ Inattention/ Failed to yield right of way/ Followed too closely/ Failure to keep in proper lane	Complete Streets Project (Sidewalk installation)	Short-Term Install midblock crosswalks with RRFBs Install transverse pavement markings near proposed midblock crosswalks Install solar speed feedback signs Install flashing LED STOP signs Newtown Road at Wakeby Road, Newtown Road at Lake Shore Drive/River Road Intersection improvements Newtown Road at Wakeby Road Install advanced warning signs for horizontal alignment Long-Term Install sidewalk facilities Enhance/install additional lighting Intersection improvements, traffic signal and multimodal accommodations Santuit
West Main Street from Falmouth Road (Route 28) to Pitchers Way	Local / MassDOT (Route 28)	1.6	 2-lane undivided roadway Sidewalk facilities Includes white edge lines 308 crashes (6 serious injuries, 6 bicyclists, 9 pedestrians) 	Operating vehicle in erratic, reckless, careless, negligent or aggressive manner/Failure to keep in proper lane/ Disregarded traffic signs, signals, road markings/ Driving too fast for conditions/ Distracted/ Inattention/ Failed to yield right of way	Complete Streets Project (Construct a new SUP) HSIP Clusters – West Main Street at Lincoln Road Main Street at Pine Street (convert to a traffic signal	Short-Term Update traffic signals; backplates with retroreflective borders, signal timing changes, modern pedestrian signal equipment West Main Street at Route 28, West Main Street at Strawberry Hill Road At existing midblock crosswalks, include RRFBs such as near The Daily Paper, east of Pine Street, and Dunkin' after The Daily Paper Long-Term Intersection improvement West Main Street at Pine Street and West Main Street at Lincoln Road (SS4A RSA location) Install a shared use path
Falmouth Road (Route 28) from Mashpee Townline to Airport Rotary	MassDOT	9.32	 2-lane undivided roadway Shared use path 1,532 crashes (6 fatal, 27 serious injuries, 17 bicyclists, and 13 pedestrian) 	Visibility obstructed/ Operating vehicle in erratic, reckless, careless, negligent or aggressive manner/ Inattention/ Failed to yield right of way/ Followed too closely/ Failure to keep in proper lane or running off road/ Disregarded traffic signs, signals, road markings/ Driving too fast for conditions	Visibility obstructed/ Operating vehicle in erratic, reckless, careless, negligent or aggressive manner/ Inattention/ Failed to yield right of way/ Followed too closely/ Failure to keep in proper lane or running off road/ Disregarded traffic signs, signals, road markings/ Driving too fast for conditions	Short-Term/Long-Term Incorporate RSA recommendations Route 28 at Bearses Way Incorporate elements of the cross sections from the Cape Cod Route 28 Corridor Study SS4A RSA Location Falmouth Road at South County Road and Falmouth Road from Old Stage Road to Phinneys Lane Incorporate recommendations from Cape Cod Commission Route 28 Cotuit Corridor Study (2017)
lyannough Road (Route 132) from Route 6 to Bearses Way	MassDOT	1.6	 4-lane divided roadway Sidewalk facilities Posted Speed Limit: 45 mph 299 crashes (1 fatal, 2 serious injuries, 1 bicyclist, 2 pedestrians) 	Failed to yield right of way/ Operating vehicle in erratic, reckless, careless, negligent or aggressive manner/ Made an improper turn/ Inattention/ Failure to keep in proper lane or running off road/ Distracted/		Short-Term Evaluate traffic signals and queuing Long-Term Install edge line rumble strips Include streetscape elements (limited ROW) Long-Term Install edge line rumble strips Include streetscape elements (limited ROW)

Town Profile

BARNSTABLE - MID CAPE

HIN – Corridor/ Intersection	Jurisdiction	Length (miles)	Characteristics	Contributing Factors	Studied/ Previous Planning	Potential Countermeasures
lyannough Road (Route 28) from Airport Rotary to Yarmouth Townline	MassDOT	0.94	 2-lane undivided roadway Limited sidewalk facilities 345 crashes (1 fatal, 2 serious injuries, 6 bicyclists, 1 pedestrian) 	Inattention/ Distracted/ Failed to yield right of way/ Followed too closely/ Operating vehicle in erratic, reckless, careless, negligent or aggressive manner/ Failure to keep in proper lane/ Followed too closely/ Exceeded authorized speed limit	Complete Streets Project (Construct a new SUP and upgrade signals) HSIP Clusters – Iyannough Road at East Main Street, Iyannough Road at Town Brook Road	Short-Term Consideration for narrow travel lanes (10-11 feet) Intersection improvements Route 28 at Yarmouth Road (TIP 606272). Route 28 at Yarmouth Road is currently under construction Long-Term Roundabout retrofit upgrades to Airport Rotary and shared use path (TIP 610926) Widen sidewalk and convert to shared-use path (TIP 608264)
Main Street (Route 6A) from Hyannis Barnstable Road to Yarmouth Townline	MassDOT	2.15	 2-lane undivided roadway Sidepath 48 crashes (3 serious injuries, 1 bicyclist) 	Operating vehicle in erratic, reckless, careless, negligent or aggressive manner/ Inattention/ Failure to keep in proper lane or running off road/ Inattention/ Followed too closely		Short-Term Identify midblock crossings with RRFBs Long-Term Include streetscape elements and lighting