


TRURO



Head of the Meadow Trail #1 (Holden Street)

CRASH HISTORY SURROUNDING THE CROSSING

No crash history surrounding the crossing.

HOLDEN STREET, ROAD SAFETY FEATURES

Dir.	Advance Warning Signs	Bike Trail Crossing Signs	Advance Pavement Markings	Control Type	Shark Teeth Yield Markings	Crosswalk Markings	Median Between Crosswalk	Additional Safety Features	Visibility of Bike Trail	Grade	Posted Speed Limit	Avg. Lane and Shoulder Width
NB	None	Good	None	None	None	Good	No	None	Good	Slight Down hill	None	13'/2'
SB	None	Good	None	None	None	Good	No	None	Good	None	None	15'/1'

HEAD OF THE MEADOW TRAIL BIKEWAY SAFETY FEATURES

Dir.	Control Type	Condition of Signage	Pavement Markings	Advance Warning Signs	Sight Distance	Width at Intersection	Median Approaching Intersection	Other Features	Crossing Distance	Crosswalk Style	Crosswalk Width	Tactile Warning Plates
EB	Stop	Good	None	Yes	Good	22'	No	None	43'	Standard	10'	Good
WB	None	None	None	No	Good	22'	No	None	43'	Standard	10'	None

EXTRA NOTES

WB approach doesn't exist, The trail begins at this crossing.

IMAGES

Figure 61: Road Approach



Figure 62: Path Approach to Crossing

